Refname	**DD:sdf.tol**
Label	Stress Distribution Factor (Function) Based on Pbtol
Units	Unitless
Equation	$J_{tol} = \log\left(\log\left(\frac{1}{1-P_{btol}}\right)\frac{\left(\frac{a}{1000}\frac{b}{1000}\right)^{m-1}}{k\left(\left(E\cdot 1000\left(\frac{h}{1000}\right)^2\right)\right)^m \cdot LDF}\right)$
Description	J_{tol} is the stress distribution factor (Function) based on Pbtol P_{btol} is the tolerable probability of breakage a is the plate length (long dimension) (m) b is the plate width (short dimension) (m) m is the surface flaw parameter ($\frac{\mathrm{m}^{12}}{\mathrm{N}^7}$) k is the surface flaw parameter ($\frac{\mathrm{m}^{12}}{\mathrm{N}^7}$) E is the modulus of elasticity of glass (Pa) h is the actual thickness (m) LDF is the load duration factor